

Share your ideas and get rewarded

In the age of open innovation, ideas platform is a vital tool for helping Al Shirawi to collect, manage, and track ideas or problem-solving strategies.



Your Email

moazzam.ali@ase.ae

Your Password

.....



User Manual

[Forgot my Password](#)

Sign in



Deepak Kumar Al Shirawi Enterprise L.L.C. - Service Machinery Equipment
Created For : Al Shirawi Enterprises LLC | Service Machinery Equipment
Continuous Improvement
2024-03-05 03:37:52

New Idea



HAMMER LINE HYDRAULIC TUBE RERUOTE

Current stage: Hammer line circuited backhoe machines having issue in removal of rear axle oil level indicator plug.
Implementation:
Informed OEM to change the hydraulic circuit connection to improve serviceability.

Idea Given By: Mr.Anoop (33343).



HAMMER LINE CIRCUIT MODIFICATION.docx
337.89 KB



Quaita Joshi

Share your Comment





Deepak Kumar | Al Shirawi Enterprise L.L.C. - Service Machinery Equipment
Created For : Al Shirawi Enterprises LLC | Service Machinery Equipment
Continuous Improvement
2024-03-28 03:04:11

New Idea



Safety Improvement

LIFTING CHAIN HOOK MODIFICATION

Model: SR130/SR150/Sr150B/SR175B/MTX-1840/MHT1740

Before:

Unable to use the lifting Chain inbuilt hook with lock.
We Use belt for offloading/loading units from truck.
Unsafe act, If balance is not obtained during offloading/loading, possibility of unit dropping from lifting belt.
We cannot install hooks with safety locks onto frame.

After:

Team consulted with Carlstel, who is the authorized provider of lifting chains with load test certificate.
We explained our requirement in detail and identified the right hooks for our application.
After Trail, implement the hook with chain, tested found ok.





Moazzam Ali Mazhar Al Shirawi Enterprise L.L.C. - Service Machinery Equipment

Created For : Al Shirawi Enterprises LLC | Machinery Equipment

Innovations

2024-04-23 07:21:40

New Idea



Exhaust System modification

One of our Key customers requested for modifications on the exhaust system to suit their operation. There was no solution available with the manufacturer. Mr. Haridas from our team stepped in. He designed & successfully tested the new exhaust system. Photos and details in the attachment.

Regards



Exhaust system modification.pdf
886.32 KB



Philip Varghese and 1 Others

Share your Comment

0

View more Comments +



Comments...

